Weathertzerfon Assistance Program

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/23023CN1716/1
Work Order Type: Weatherization

Audit Name: 23023CN1716AUDIT

CLIENT INFORMATION

Client ID: 23023CN1716

AGENCY INFORMATION

Client ID: 23023CN1716

Agency: Chattanooga Neighborhood Enterprise, Inc. Agency Phone: (423) 756-6201

Address: 1301 Market Street, Suite 100 **Fax:** (423) 756-3851

Company Name & License I	lumber:		
Contractor's Signature:			

COMMENT

Measures

1	Measure 1		approx 88 sq ft of R 13 lation to interior walls		II.	Componen	ts		1	nspected
C	omment									
						Estimated	<u> </u>		Actual	
#	Material / Lab	oor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified		Misc Material	Each	1					
0	Other Detail							7		
					Measur	e Sub Total:			Sub Total:	
	Measure 2 omment	Repl x 12	ace 1 broken pane WD in	11 approx	x 10	Componen				Inspected
C	omment	x 12	in	11 approx		Estimated			Actual	
C	omment Material / Lab	x 12	in Description / Comment	Units	2 10 Qty	-		Qty		Inspected
C :	omment	x 12	in			Estimated	<u>'</u>	Qty	Actual	
C # 10	omment Material / Lab	x 12	in Description / Comment	Units	Qty	Estimated	<u>'</u>	Qty	Actual	
C # 10	omment Material / Lab Unspecified	x 12	in Description / Comment	Units	Qty	Estimated	<u>'</u>	Qty	Actual	
C # 10	omment Material / Lab Unspecified	x 12	in Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u>'</u>		Actual Unit Cost	
C # 10	omment Material / Lab Unspecified	x 12	in Description / Comment	Units Each	Qty 1	Estimated	<u>'</u>		Actual	

Measure 3		lace 1 broken pane WD inch	5 approx	10	Componen	its			Inspected
Comment					Estimated	ı		Actual	
# Material / L	abor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecifie	b	Misc Material	Each	1					
Other Detail					1		7		
				Measu	re Sub Total:			Sub Total:	
Measure 4	-	lace 2 broken panes in			Componen	nts			Inspected
Measure 4 Comment	-	lace 2 broken panes in ner basement window a			·				Inspected
	cori	ner basement window a		x 12	Component Estimated Unit Cost		Qty	Actual Unit Cost	Inspected
Comment	cori	-	pprox 10		Estimated	<u> </u>	Qty	Actual	
Comment # Material / L 10 Unspecifie	cori	ner basement window a Description / Comment	upprox 10	x 12 Qty	Estimated	<u> </u>	Qty	Actual	
Comment # Material / L	cori	ner basement window a Description / Comment	upprox 10	x 12 Qty	Estimated	<u> </u>	Qty	Actual	
Comment # Material / L 10 Unspecifie	cori	ner basement window a Description / Comment	upprox 10	x 12 Qty	Estimated	<u> </u>	Qty	Actual	
Comment # Material / L 10 Unspecifie	cori	ner basement window a Description / Comment	Units Each	Qty 1	Estimated	<u> </u>		Actual	
Comment # Material / L 10 Unspecifie	abor	ner basement window a Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / La 10 Unspecifie Other Detail	abor	ner basement window a Description / Comment	Units Each	Qty 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Measure 5		lace 2 broken panes in 12 in	WD1 app	rox	Componen	ts			Inspected
Comment					Estimated	1		Actual	
# Material / La	bor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified		Misc Material	Each	1					
Other Detail							7		
] []		
				Measur	e Sub Total:]	Sub Total:	
Field Notes:									
Measure 6	Ren	lace 2 broken nanes WI	D4 approx	x 10	Componen	nts.			Inspected
Measure 6 Comment	Rep x 12	lace 2 broken panes WI in	D4 approx	x 10	Componen	its			Inspected
	-	-	D4 approx	x 10	Componen Estimated			Actual	Inspected
Comment # Material / La	x 12	Description / Comment	Units	x 10	-		Qty		Inspected Total
Comment # Material / La	x 12	in			Estimated	1	Qty	Actual	
Comment # Material / La	x 12	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Comment # Material / La 10 Unspecified	x 12	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Comment # Material / La 10 Unspecified	x 12	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Comment # Material / La 10 Unspecified	x 12	Description / Comment	Units Each	Qty 1	Estimated	1		Actual	
Comment # Material / La 10 Unspecified	x 12	Description / Comment	Units Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	
# Material / La 10 Unspecified Other Detail	x 12	Description / Comment	Units Each	Qty 1	Estimated Unit Cost	1		Actual Unit Cost	

Measu		PLACE GRILL ON RETU er size	RN 20 x 3	0 in	Componen	ts		1	Inspected
Comme	nt								
					Estimated			Actual	
# Materia	l / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspe	cified	Misc Material	Each	1					
Other De	tail								
				Measur	e Sub Total:			Sub Total:	
Measul Comme		iltration Redctn			Componen				Inspected
		iltration Redctn			Componen Estimated			Actual	Inspected
	nt	iltration Redctn Description / Comment	Units	Qty	-		Qty		Inspected Total
Comment	nt al/Labor		Units Each	Qty 1	Estimated	<u>'</u>	Qty	Actual	
Comment	nt al / Labor laneous S	Description / Comment		_	Estimated	<u>'</u>	Qty	Actual	
# Materia 10 Miscell	nt al / Labor laneous S	Description / Comment		_	Estimated	<u>'</u>	Qty	Actual	
# Materia 10 Miscell	nt al / Labor laneous S	Description / Comment		_	Estimated	<u>'</u>	Qty	Actual	
# Materia 10 Miscell	nt al / Labor laneous S	Description / Comment	Each	1	Estimated	<u>'</u>		Actual	

	Measure 9 Attic	Ins. R-38			Componen	ts A1			Inspected
					Estimated	1		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	2160					
2	Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	2160					
3	Miscellaneous Sup	Added Misc Cost	Each	1					
C	Other Detail								
L									
				Measure	e Sub Total:			Sub Total:	
	Field Notes:								
	Field Notes: Measure 10 DWH	l Tank Insulation			Componen	ts			Inspected
	Measure 10 DWH	l Tank Insulation			Componen Estimated			Actual	Inspected
C	Measure 10 DWH	Tank Insulation Description / Comment	Units	Qty	-		Qty		Inspected Total
<i>C</i>	Measure 10 DWH comment Material / Labor		<i>Units</i> Each		Estimated	1	Qty	Actual	
C # 1	Measure 10 DWH comment Material / Labor	Description / Comment		Qty	Estimated	1	Qty	Actual	
C # 1	Measure 10 DWH comment Material / Labor Hot Water Equipm	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Measure 10 DWH comment Material / Labor Hot Water Equipm Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Measure 10 DWH comment Material / Labor Hot Water Equipm Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Measure 10 DWH comment Material / Labor Hot Water Equipm Labor	Description / Comment DHW Tank Insulation	Each Each	Qty 1 1	Estimated	1		Actual	
C # 1	Measure 10 DWH comment Material / Labor Hot Water Equipm Labor	Description / Comment DHW Tank Insulation	Each Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
C # 1	Measure 10 DWH comment Material / Labor Hot Water Equipm Labor Other Detail	Description / Comment DHW Tank Insulation	Each Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Measure 11 D	WH Pipe Insulation			Componen	ts			Inspected
Comment								
				Estimated	·		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail]]		
			Measure	e Sub Total:			Sub Total:	
Field Notes:								
Measure 12 Fl	oor Ins. R-19			Componen	ts F1			Inspected
Comment								
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation		0						
	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	2160					
2 Labor	Fiberglass Faced Batt - R-19 Floor Insulation -	SqFt SqFt	2160 2160					
2 Labor	Fiberglass Faced Batt - R-19							
2 Labor Other Detail	Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -							
2 Labor Other Detail	Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -							
	Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt	2160					
	Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt	2160	e Sub Total:			Sub Total:	
	Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt	2160	e Sub Total:			Sub Total:	
Other Detail	Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt	2160	e Sub Total:			Sub Total:	

Meas		CO Monitors is Needed b I living area	oasement		Componen	ts		1	nspecte
Comm	nent				Estimated			Actual	
# Mate	erial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Uns _i	pecified	See the User Defined Measure for a list of materials.	Each	1					
Other I	Detail						1		
				Measur	e Sub Total:] ;	Sub Total:	
Comm		Improper Venting (Cloth	nes Diyei		Componen Estimated			Actual	nspecte
# Mate	erial / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
0 Uns	pecified	See the User Defined	Each	1					
		Measure for a list of materials.							
Other I	Detail								
Other I	Detail								
Other I	Detail								
Other I	Detail			Measur	e Sub Total:			Sub Total:	

I	Measure 15 Fix Fan	Improper Venting Kitch	en Exhau	st	Componen	ts		ı	Inspected
C	omment								
					Estimated	<u> </u>		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10	Unspecified	See the User Defined Measure for a list of materials.	Each	1					
C	Other Detail								
				Measur	e Sub Total:] ,	Sub Total:	
	Field Notes:								
	16 40 E				<u> </u>	4-			Inchested
		Improper Venting of Bar aust Fan	throom		Componen			Actual	Inspected
C	Exh comment	aust Fan	throom	Qty	Estimated		Qty		Inspected
<i>C</i>	Exh	Description / Comment See the User Defined		Qty 1	-		Qty	Actual	
<i>C</i>	Exh comment Material / Labor	aust Fan Description / Comment	Units		Estimated		Qty	Actual	
C # 10	Exh comment Material / Labor Unspecified	Description / Comment See the User Defined Measure for a list of	Units		Estimated		Qty	Actual	
C # 10	Exh comment Material / Labor	Description / Comment See the User Defined Measure for a list of	Units		Estimated		Qty	Actual	
C # 10	Exh comment Material / Labor Unspecified	Description / Comment See the User Defined Measure for a list of	Units		Estimated		Qty	Actual	
C # 10	Exh comment Material / Labor Unspecified	Description / Comment See the User Defined Measure for a list of	Units Each	1	Estimated			Actual	

(Wal	tice Lead Safe Weathe ls)	rization		Componen	ts		1	Inspect
Comment				Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Unspecified	See the User Defined Measure for a list of materials.	Each	1		rotar			Total
Other Detail]		
] []		
			Measur	e Sub Total:]	Sub Total:	
Measure 18 Pres Comment	sureRelief Piping Need	led		Componen			1	Inspecto
Comment				Estimated	1		Actual	
	Description / Comment	Units Each	Qty 1	•		Qty		Total
Comment Material / Labor Health and Safety	Description / Comment	Units	_	Estimated	1	Qty	Actual	
Comment Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated	1	Qty	Actual	
Comment Material / Labor	Description / Comment Pressure relief piping	<i>Units</i> Each	1	Estimated	1	Qty	Actual	
Comment Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	Units Each Each	1 1	Estimated	1		Actual	
Comment Material / Labor Health and Safety Labor	Description / Comment Pressure relief piping	Units Each Each	1 1	Estimated Unit Cost	1		Actual Unit Cost	